0/12

· ICRET

IN 31271

TOR: 19/1854Z DEC 68 WP

25X1A

S E C R E T 191815Z DEC 68 CITE

25X1A

25X1A

25X1A

IDEALIST

FOR:

SUBJ: CANOPY LATCH MECHANISM

CLOSE INSPECTION OF THE CANOPY LATCH MECHANISM ON ARTICLE 053
REVEALED RIGGING SLIGHTLY OUT BUT NOT ENDUGH TO PERMIT CANOPY TO
OPEN. CONCLUSION AFTER INSPECTION IS THAT CANOPY WAS NOT FULLY
CLOSED AND LATCHED. SUGGEST THE FOLLOWING STEPS ON ALL AIRCRAFT:

- 1. INSPECT CANOPY LATCH MECHANISM FOR PROPER RIGGING PER TM-U2R-2-2.
- 2. AFTER PILOT IS IN PLACE AND CANOPY CLOSED, INSPECT OUT-SIDE CANOPY RELEASE HANDLE INDICATOR LINES FOR PROPER ALIGNMENT.

END OF MSGS

U/

4

IN 31271

SECRET